

屏東縣歷史災情紀錄表

回報日期：115 年 08 月 24 日 08:56		災情類別：水利設施災情（豪雨事件）
地點：九如鄉玉泉街 18 巷附近		回報人員：EMIC／九如鄉公所回報
項次	災情說明	勘查照片
1	水閘門長年鎖住，排水逆流進農地。	 <p>The first photograph shows a concrete water gate structure completely blocked by a dense growth of tall green grass and weeds. Water is visible flowing through the narrow opening behind the gate. The second photograph is a close-up of the gate's mechanism, showing a metal handle and a wooden beam, both heavily overgrown with thick vegetation, preventing the gate from being opened.</p>