

屏東縣歷史災情紀錄表

回報日期：115 年 08 月 23 日 13:39		災情類別：交通阻斷（豪雨事件）
地點：三地門鄉 185 線口社大橋		回報人員：防災士／劉○雯回報
項次	災情說明	勘查照片
1	河川水位高漲，口社大橋預警性封橋。	 <p>The photographs show a river with high, turbulent water levels. In the background, a bridge is visible, partially obscured by the water. The sky is overcast and grey, indicating a storm or heavy rain event. The water appears dark and churning, with white foam visible in some areas. The bridge structure is concrete and has multiple spans. The surrounding area includes some greenery and trees on the banks.</p>